

How to load in a Firmware update to the Wolverine PD20

1. Copy firmware file PHOTO20-PS681C-BS...-PD108.elf to an SD/SDHC card **Root Directory**
2. Insert SD card into the PD20
3. Power on the PD20



4. Press and **hold** the LEFT Arrow button and press CONVERT button



5. Release buttons when you see **Setup Options** screen
6. Press the LEFT Arrow button to highlight **FW Upgrade**



7. Press OK/Enter button
8. Wait for the unit to load in Firmware and reboot

PS: If the PD20 is not loading the Firmware it could be because the Firmware file is not placed in the Root Directory. Do not insert the Firmware file under any folder.

For further help contact Tech Support at support@wolverinedata.com or M-F 9:00-5:00 PST at 949-458-9888.